

Storage and handling of Nyloprint Polymere plates

(Direct laser engraved (DLE) and laserexposed HD CDI)

- Protect the plate surface from any damage, also during storage.
- Store the plates dark, wrapped in plastic and away from UV light.
- The polymere plates should be stored around 60% humidity.
- Contact with water will destroy the plates, air con will dry them out.
- Too much direct UV light causes the plates to dry out.
- Clean the plates IMMEDIATELY after printing. Dried ink can damage the plate.
- Clean the plates with one of the recommended cleaning liquids.
- For cleaning use :
 - * soft brush
 - * brush connected to a hose with cleaning fluid or a special fabric /for example : www.flexwell.de)
- **DO NOT RUB THE PLATES WITH A CLOTH, IT WILL DAMAGE THE HIGHLIGHT DOTS!**
- **Most of the damage comes from too hard handling when cleaning the plates.**